

## TOOLS RENEWED DUST CONTROL

### WET OPTION: Air tool spray mist

- Connect spray hose/mister assembly to water supply.
- Water mist keeps silica dust movement to a minimum.
- Dispose of residue with other tailings.



### DRY OPTION: VDEX Vacuum System

- Connect shroud to your tool
- Connect Air Powered Wet Vacuum
- Dust is caught in the vacuum tank and disposed in your dumpster.

**VDEX™  
MEETS OR EXCEEDS  
OSHA REQUIREMENTS**



VDEX attachment for Rivet Busters and Chipping Hammers



**JAC-3P**  
Venturi Vacuum  
Complete with Pall & 1-1/4" x 10 ft  
Anti-Static Vacuum Hose with  
Grounding Wire

Tools Renewed Inc

Tel: 860-665-8155 email: [sales@toolsrenewed.com](mailto:sales@toolsrenewed.com) web: [www.toolsrenewedparts.com](http://www.toolsrenewedparts.com)